Checking

for semi and fully automated processes

> Terminals 3030, 3010, 3720 and 3710 also provide control functions
> Pass/fail control
> Dynamic weighing, discharge with pusher, soft or compressed air
> Classifying
> Completeness control, overload control
> Pick location control
> Software "Checking by statistics" for 3030 program terminal, see page 150

Example of applications:

Pass/fail control scale with integrated conveyor belt

> Target value input with tolerances at terminal, place weighing goods on scale, automatic removal
  Good = counter-clockwise rotation / bad = clockwise rotation
> Weighing range: 200 g / scale interval 0.1 g
> Dimension weighing belt: 300 x 130 mm

Scope of supply:
> 3030 Program terminal with continuous weighing software
> Accessories 3030: I/O card, wall/stand bracket, relay box with power supply
> Weighing platform 2890
> Conveyor system complete with control module motor

Continuous scale with conveyor belt for pass/fail control

> Checking without belt stop with pusher in the course of operation
> Conveying, control and weighing technology from one source
> Can be integrated into existing production lines and conveyor systems
> 100% control with injection molded parts, in assembly and packaging processes

Scope of supply:
> 3030 Program terminal with continuous weighing software
> Accessories 3030: I/O card, wall/stand bracket, relay box with power supply
> Weighing module with DMS load cells
> Conveyor systems complete with control module motor, conveyor belts specifically developed for weighing applications for industrial purposes
> Pusher for discharging parts having an incorrect weight
> Base frame to achieve the desired working height